
Product Information





Pictures/figures show packaging and label of the product. Note that label shown above may not be of the latest revision.

Shipment Packaging Instructions:

The product should always be packed in a large carton box.

The box should be appropriately sized so that the bags fit nicely in the box without extra space for them to move around.

Storage temperature: -20°C (-4°F) TO +50°C (122°F).

Humidity: 10-95% (non-condensing)

Pressure: 700 hPa to 1060 hPa

